



# Elevator #6 Photos




Elevator #6 Machine Room

# Elevator #6 Photos



Existing Otis Hydraulic Power unit to be Re-used

# Elevator #6 Photos



External Door and Floor Status Relays (Located within Machine Room)